


OrderPlans

Lidar Scan-to-Plan Solutions


These examples showcase anomalies revealed during the in-depth analysis of various properties. Detecting these building intricacies early on empowers the design professionals to seamlessly incorporate mitigative measures into the proposed scope of work, steering clear of surprise change orders in the midst of construction. The commitment to this proactive approach not only ensures a smoother project journey but also shields homeowners from unnecessary loss of time and resources. Our aim is to help you build with foresight, safeguarding your vision and investment from the start.



A STEP UP INTO THE ADDITION
WAS BUILT INTO THE DESIGN
AS A SOLUTION





AREA OF PROPOSED
MASTER SUITE



HIGHER CEILING IN THIS AREA DID NOT ALLOW FOR
THE REQUIRED STRUCTURE







GARAGE AND STORAGE AREA
2 DEGREES OUT OF SQUARE
FROM THE MAIN BUILDING



OrderPlans
Lidar Scan-to-Plan Solutions

FLOOR AND CEILING CROOKED
AND NOT IN ALIGNMENT WITH THE
REST OF THE HOUSE

FLOOR CROOKED
AND NOT IN ALIGNMENT WITH THE
REST OF THE HOUSE

FLOOR CROOKED
AND NOT IN ALIGNMENT WITH THE
REST OF THE HOUSE

